



MANAGEMENT SYSTEM CERTIFICATE

Certificate no.:
C543919

Initial certification date:
17 August 2022

Valid:
17 August 2022 – 16 August 2025

This is to certify that the management system of

Constructora y Perforadora Latina S.A. de C.V.

Av. Isla de Tris – Takin Parque Corporativo 4 ½ (3er Piso) Fracc. Residencial San Miguel.,
CP.24157, Ciudad del Carmen, Campeche, Mexico

and the sites as mentioned in the appendix accompanying this certificate

has been found to conform to the Quality Management System standard:
ISO 9001:2015

This certificate is valid for the following scope:

Leasing and Integral Maintenance Services of Marine Platforms and Inland Drilling Equipment, as well as Drilling, Cementation, Completion and Repair of Wells in Marine and Terrestrial Operations including exploration, development, production and abandonment of oil fields for the energy sector.

Place and date:
Ciudad de México, 24 August 2022

For the issuing office:
DNV - Business Assurance
Av. Insurgentes Sur 859, Piso 7, Col. Nápoles,
C.P. 03810, Ciudad de México, Mexico



Mauricio Venturin
Management Representative

Lack of fulfilment of conditions as set out in the Certification Agreement may render this Certificate invalid.

ACCREDITED UNIT: DNV México S.A. de C.V., Av. Insurgentes Sur 859, Piso 7, Col. Nápoles, C.P. 03810, Ciudad de México, Mexico - TEL: +52 (55) 8526 8900.
assurance.dnv.com

Appendix to Certificate

Constructora y Perforadora Latina S.A. de C.V.

Locations included in the certification are as follows:

Site Name	Site Address	Site Scope
Perfolatina S.A de C.V. / CPL Servicios de Perforación S.A. de C.V. (Poza Rica)	Blvd. Adolfo Ruiz Cortines 1708 Col. Benito Juárez, C.P. 93310, Poza Rica de Hidalgo, Veracruz, Mexico	Integral Services of support to the Drilling, Completion, Repair, Cementation, Introduction of Oil Well Casing Pipe and Tubular Inspection of Terrestrial Wells, Surface Control Connections, Cementation Laboratories and Development of oil fields. Lease with Integral Maintenance of Equipment, Drilling, Completion and Repair of Marine Oil Wells.
Perforaciones Marítimas Latina S.A de C.V. (Villahermosa)	Av. Adolfo Ruiz Cortines N° 1344 Torre DG, piso 1 Col. Tabasco 2000, C.P. 86035, Villahermosa, Centro, Tabasco, Mexico	Planning, Design and Coordination of Offshore Operations for the Drilling, Repair and Completion of Marine Wells.
Constructora y Perforadora Latina S.A. de C.V.	Av. Isla de Tris – Takin Parque Corporativo 4 ½ (3er Piso) Fracc. Residencial San Miguel., CP.24157, Ciudad del Carmen, Campeche, Mexico	Planning and coordination for the lease with integral maintenance of marine platforms, as well as Drilling, Completion and Repair of Marine Oil Wells.